

R.N	Name of the location	DTR rating	Activity	ate of complitio
1	Thorat mala DP 1 DTC no 4064830	100KVA	DP jumps replaced 50sqmm cable with crimped AL lugs (HT line to DO fuse link & DO link to transformer booshing ,sleeved DO fuse link)	13.12.2010
2	Thorat mala DP 2 DTC no 4064831	100KVA	DP jumps replaced 50sqmm cable with crimped AL lugs (DO link to transformer booshing)and sleeved DO fuse link	22.02.2011
3	Lendi DP near khodad	100KVA	DP jumps replaced 50sqmm cable with crimped AL lugs (HT line to DO fuse link & DO link to transformer booshing ,sleeved DO fuse link)	05.08.2010
4	Khodad Gaothan DP near temple	100KVA	DP jumps replaced 50sqmm cable with crimped AL lugs (HT line to DO fuse link & DO link to transformer booshing ,sleeved DO fuse link)	22.09.2010
5	Gadhaowadi DP khodad near meen	100KVA	DP jumps replaced 50sqmm cable with crimped AL lugs (DO link to transformer booshing)and sleeved DO fuse link	18.10.2010
6	Ganghale mala DP near C13 GMRT	100KVA	DP jumps replaced 50sqmm cable with crimped AL lugs (DO link to transformer booshing)and sleeved DO fuse link	29.11.2010
7	Inam mala DP no 1	100KVA	DP jumps replaced 50sqmm cable with crimped AL lugs (HT line to DO fuse link & DO link to transformer booshing ,sleeved DO fuse link)	20.04.2011
8	Inam mala DP no 2	100KVA	DP jumps replaced 50sqmm cable with crimped AL lugs (HT line to DO fuse link & DO link to transformer booshing ,sleeved DO fuse link)	12.12.2010
9	Bermala DP no 1	100KVA	DP jumps replaced 50sqmm cable with crimped AL lugs (HT line to DO fuse link & DO link to transformer booshing ,sleeved DO fuse link)	12.09.2011
10	Malwadi DP no 2 DTC no 4064829.	100KVA	DP jumps replaced 50sqmm cable with crimped AL lugs (HT line to DO fuse link & DO link to transformer booshing ,sleeved DO fuse link)	27.01.2011
11	Garmala	100KVA	DB box replaced with fuse & isolator switch, replacing 70 sqmm cable from transformer booshing to DB box with AL crimped lugs	23.11.2010
12	Belhekar DP	100KVA	DB box replaced with fuse & isolator switch, replacing 70 sqmm cable from transformer booshing to DB box with AL crimped lugs	23.11.2010
13	Mulemala no 1	200 KVA	DB box replaced with fuse & isolator switch, replacing 70 sqmm cable from transformer booshing to DB box with AL crimped lugs ,DTC re earthing	23.11.2010

14	Waman Wasti No 1	100 KVA	DB box replaced with fuse & isolator switch, replacing 70 sqmm cable from transformer booshing to DB box with AL crimped lugs	23.11.2010
15	Kalewasti No 4	100 KVA	DB box replaced with fuse & isolator switch, replacing 70 sqmm cable from transformer booshing to DB box with AL crimped lugs	23.11.2010
16	Thorat mala No 2	100 KVA	DB box replaced with fuse & isolator switch, replacing 70 sqmm cable from transformer booshing to DB box with AL crimped lugs	23.11.2010
17	Lende Gaothan	100 KVA	DB box replaced with fuse & isolator switch, replacing 70 sqmm cable from transformer booshing to DB box with AL crimped lugs	23.11.2010
18	Vitbhatti	100 KVA	DB box replaced with fuse & isolator switch, replacing 70 sqmm cable from transformer booshing to DB box with AL crimped lugs	23.11.2010
19	Telephone DP	100 KVA	DB box replaced with fuse & isolator switch, replacing 70 sqmm cable from transformer booshing to DB box with AL crimped lugs ,DTC re earhing	23.11.2010
20	Bermala No 1	100 KVA	DB box replaced with fuse & isolator switch, replacing 70 sqmm cable from transformer booshing to DB box with AL crimped lugs	23.11.2010
21	Bermala No 2	100 KVA	DB box replaced with fuse & isolator switch, replacing 70 sqmm cable from transformer booshing to DB box with AL crimped lugs	23.11.2010
22	Bermala No 3	100 KVA	DB box replaced with fuse & isolator switch, replacing 70 sqmm cable from transformer booshing to DB box with AL crimped lugs	23.11.2010
23	Inam mala No 1	100 KVA	DB box replaced with fuse & isolator switch, replacing 70 sqmm cable from transformer booshing to DB box with AL crimped lugs ,DTC re earhing	23.11.2010